

DEPARTMENT/DIVISION/PROJECT XAS 17-BM

QA CLASSIFICATION: ☐ A1 (CRITICAL/HIGH) ☐ A2 (MAJOR/MODERATE) ☐ A3 (MINOR/LOW) ☐ A4 (NEGLIGIBLE)

PART NAME:	Pink beam slits, Be exit Window, beam absorber		
PART NO.:	Oxford, BNL,	REV.:	
PREPARED BY:	Michael Sullivan	DATE:	February 2018
VENDOR:	N/A	P.O. NO.:	
QTY. RECD.:	N/A	DATE RECD.:	

COMMENTS:

☐ Inspection/Test Data Attached (Data Sheet To Include: Part Name, Part No., Date, & Sheet ____ of ____)

ITEM	CHARACTERISTIC/REQUIREMENT	INSP. / REJ.	INSPECTOR'S SIGNATURE/LIFE #	DATE
1	Oxford Pink beam slits- Pressure test to 150psi hold for 30 minutes with no pressure loss	OK /	Mike Sullivan S-5438	2-2018
2	Pink beam absorber- Pressure test to 150psi hold for 30 minutes with no pressure loss	OK /	Mike Sullivan S 5438	2-2018
3	Beryllium exit window- Pressure test to 150psi hold for 30 minutes with no pressure loss	OK /	Mike Sullivan S 5438	2-2018
4		/		
5		/		
6		/		
7		/		
8		/		
9		/		

Record all nonconformances for each item on page 2 of ITR.

Qty. Accepted 3 PARTS Serial (LOT) No. Accepted _____